


4. Re-install ring, hardware and drain cover.

DETAIL: TPO Low Slope Roof

GENERAL DETAILS - DRAIN - ROOF COATING RESTORATION

This detail drawing is intended to show the generally recommended procedure for dealing with the condition shown. Actual field conditions may vary. When such conditions vary slightly from the drawing, the intent and industry best practices are to be used. Any question, contact Aldo Products Company, Inc., Technical Department.

Contact Aldo Products Company, Inc., for assistance.



DATE: JANUARY 2018 DRAWN BY: TECHNICAL SUPPORT SCALE: NONE