


DETAIL: Modified Bitumen (Mod Bit) Low Slope Roof

GENERAL DETAILS – SEAMS – ROOF COATING RESTORATION

This detail drawing is intended to show the generally recommended procedure for dealing with the condition shown. Actual field conditions may vary. When such conditions vary slightly from the drawing, the intent and industry best practices are to be used. Any question, contact Aldo Products Company, Inc., Technical Department.



DATE: JANUARY 2018

DRAWN BY: TECHNICAL SUPPORT

SCALE: NONE

Aldo Products Company, Inc. • 1320 Litton Drive • Salisbury, NC 28147 • (800) 474-6019 • www.AldoProducts.com