


## **DETAIL: EPDM Low Slope Roof**

GENERAL DETAILS - DRAIN - ROOF COATING RESTORATION

This detail drawing is intended to show the generally recommended procedure for dealing with the condition shown. Actual field conditions may vary. When such conditions vary slightly from the drawing, the intent and industry best practices are to be used. Any question, contact Aldo Products Company, Inc., Technical Department.



Option: If required by specification, ALDOSEAL fabric is used in a three course application method with ALDOSEAL product of choice.

Contact Aldo Products Company, Inc., for assistance.

DATE: JANUARY 2018

positive water drainage.

4. Re-install ring, hardware and drain cover.

DRAWN BY: TECHNICAL SUPPORT

SCALE: NONE